

Release Note CODESYS V3.5 SP18 Patch 2

03.06.2022

1 Release Notes

| Кеу | Summary | Release Note | Component/s |
|-----------|--|---|----------------------------|
| CDS-81452 | CmpBlkDrvTcp: Possible socket blocking DoS vulnerability | [[GENERAL]] For more details see Advisory 2022-09, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=17128&token=bee4d 8a57f19be289d623ec90135493b5f9179e3 &download= | CODESYS Control |
| CDS-81453 | Runtime: Possible channel blocking DoS vulnerability | [[GENERAL]] For more details see Advisory 2022-09, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=17128&token=bee4d 8a57f19be289d623ec90135493b5f9179e3 &download= | CODESYS Control |
| CDS-81306 | OPC Server: Secure password used for PLC login | [[GENERAL]] For more details see Advisory 2022-10, which is available on the CODESYS website: https://customers.codesys.com/index.php? elD=dumpFile&t=f&f=17129&token=1c148 5c4a700c04f2069699f5be7558d276ca117 &download= [[COMPATIBILITY_INFORMATION]] See manual of the CODESYS OPC DA Server, section OPC Config Tool, to learn more about compatibility and restrictions. | OPC Server, PLC Handler |
| CDS-56565 | UTF-8 Encoding for STRINGs | [[GENERAL]] There is now a compiler option to change the encoding of the data type STRING. With the option checked, a STRING will be interpreted as encoded in UTF-8. I.e. any | CODESYS |



| | | STRING literal 'asdf' will be encoded in UTF-8. Monitoring of STRING will decode STRING-values from UTF-8. | |
|-----------|---|---|---------|
| | | Alternatively it is possible to mark only specific string literals as UTF-8. This is accompanied by new monitoring attributes to have a strings content monitored as UTF-8 explicitly. | |
| | | The Static Analysis Light and the compiler also have additional checks and rules for detecting cases where the new UTF-8 option should be enabled. They also have new checks for strings operations which might only work on ASCII strings but not on UTF-8 strings anymore. | |
| CDS-63824 | Setup: Uninstallation should delete installation folder | [[GENERAL]] New property CDS_DELINSTALLDIR can be set at installation 1=Delete the destination folder INSTALLDIR at uninstall (Default) 0=Do not delete destination folder INSTALLDIR at uninstall If INSTALLDIR at uninstall If INSTALLDIR is not a subfolder of ProgramFiles or ProgramFiles(x86), INSTALLDIR is not deleted regardless of CDS_DELINSTALLDIR For more information see the documentation "CODESYS Installation OEM Adaptations" and "CODESYS Installation Extended OEM Adaptions" | CODESYS |
| CDS-65416 | AP-UserManagement: Group derivation does not work | [[GENERAL]] As the "group in group" concept was removed from the runtime with CDS- 65415, the possibility to configure having a group within a group was also removed from the IDE. So now a group will only contain users as members. | CODESYS |
| CDS-71854 | Package Manager: Check Dependencies always | [[GENERAL]] Dependencies (MinimumPlugin, MaximumPlugin or MinimumProfile) will now be evaluated independently from the package's content. In previous version | CODESYS |



| | | these depenencies were only be checked if there is a profile relevant content include (ProfileChange, AddMenuConfiguration, AddToolBarConfiguration,). | |
|-----------|---|---|---------|
| | | [[COMPATIBILITY_INFORMATION]] | |
| | | If these dependencies has been used without any profile relevant content the installation will fail now. | |
| CDS-77156 | BinaryFormatter: Vulnerability caused by deserialization of untrusted culture settings | [[GENERAL]] For more details see Advisory 2021-13, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=16805&token=ee583 c498941d9fda86490bca98ff21928eec08a &download= | CODESYS |
| CDS-77163 | AccessDenied exceptions during setup or CODESYS startup | [[GENERAL]] ShadowCopy was deactivated for the executables CODESYS, PackageManager, PackageManagerCLI and IPMCLI Every call to one of this executables will result in a selfcall to the same executable, in which the called function is executed. In the wrapping call all files which need to be copied are copied after the inner call finished execution. If an error occurs during the copy operations a rollback is performed. If this rollback is not possible or fails, the installation will be marked as corrupted and a reinstall will be required. [[COMPATIBILITY_INFORMATION- OEM]] Having removed the .Net Shadow Copy mechnism may lead to access denied exceptions within OEM code trying to overwrite assemblies that are currently loaded. This may occur with OEM plugins running in a standard CODESYS executable during installation of plugins or packages via Autmation Platform API. Not affected are custom OEM executables still having .Net Shadow Copy active and installations via PackageManager or IPM executables. | CODESYS |
| CDS-77324 | Compiler, Download: Erroneous behavior after | [[GENERAL]] | CODESYS |
| | | Compiler Version >= 3.5.18.0 | |



| | | I | |
|-----------|--|---|---------|
| | download regarding variable values | The compiler calculates the result of constant expressions during compile time. The fix may lead to different calculations, and this can lead to a different behavior of the application. Especially in cases, where intermediate results of the calculation exceed the type Range of some of the constants in the expression. The Compiler now calculates the expression as LINT- expression or ULINT-expression and casts the result as used in the expression. In this case a complex expression is evaluated the result is cast to LINT and assigned to an LINT. | |
| CDS-77359 | BinaryFormatter: | [[GENERAL]] | CODESYS |
| | Vulnerability caused by deserialization of untrusted profile data | For more details see Advisory 2021-13, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=16805&token=ee583 c498941d9fda86490bca98ff21928eec08a &download= | |
| CDS-77364 | BinaryFormatter: | [[GENERAL]] | CODESYS |
| | Vulnerability caused by deserialization of untrusted data in the package management | For more details see Advisory 2021-13, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=16805&token=ee583 c498941d9fda86490bca98ff21928eec08a &download= | |
| CDS-77365 | BinaryFormatter: | [[GENERAL]] | CODESYS |
| | Vulnerability caused by deserialization of untrusted "MissingTypes" data | For more details see Advisory 2021-13, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=16805&token=ee583 c498941d9fda86490bca98ff21928eec08a &download= | |
| CDS-78280 | Menu PackageManager should be replaced by Installer | [[GENERAL]] If an CODESYS Installer with a version equal or higher than 1.2.0 is installed, the menu entry Tools -> PackageManager is replaced with Tools -> CODESYS Installer Instead of the PackageManager this new entry will open the CODESYS Installer to manage the packages of the current installation. A new Customization Hook was | CODESYS |



| | | introduced ("PackageManagement", | |
|-----------|---|--|-----------------|
| | | "DoNotUseInstaller"), if set to true the | |
| | | PackageManager entry will be used even | |
| | | if the CODESYS Installer is installed in a | |
| | | version higher or equal to 1.2.0 | |
| CDS-78571 | Package import from | [[GENERAL]] | CODESYS |
| | previous installation | | |
| | breaks package signature | Packages have been removed from the | |
| | | import assistent. Packages can be easily | |
| | | installed via CODESYS Installer. | |
| | | Furthermore required Packages (Add-ons) | |
| | | will be checked during project analysis | |
| | | during project load. | |
| CDS-79032 | ProjectSource: Creating a new project as library will | [[COMPATIBILITY_INFORMATION- OEM]] | CODESYS |
| | result in a project | | |
| | | The methods Engine.CreateProject() | |
| | | always change the file extension always to | |
| | | ".project" but now it only does it if the file | |
| CDS-80861 | Drojaat open is not | extension is different to ".library". | CODESYS |
| CD3-00001 | Project open is not possible on Win8.1 32bit | [[GENERAL]] | CODESTS |
| | | Since the market share of Windows 8.1 is | |
| | | relatively small and a simple fix exists, the | |
| | | issue is not resolved. | |
| | | | |
| | | Installing .Net Framework 4.7.2 or 4.8 will | |
| | | fix this issue. | |
| CDS-31565 | CmpDevice: Multisession | [[COMPATIBILITY_INFORMATION- | CODESYS Control |
| | management needed | OEM]] | |
| | 5 | | |
| | | The CODESYS Control runtime now | |
| | | supports more than one session on a | |
| | | channel. This allows the CODESYS | |
| | | Webvisu to authenticate multiple sessions | |
| | | independently on a single communication | |
| | | channel. As a result, there is no longer a | |
| | | strict 1:1 mapping between session and | |
| | | communication channel in the CODESYS | |
| | | protocol. | |
| | | | |
| | | | |
| | | | |
| | | Accordingly, the functions | |
| | | DevGetSessionId() and | |
| | | ServerGetSessionId(), which provided the | |
| | | associated session for a channel, can no | |
| | | longer be implemented in a meaningful | |
| | | way and have therefore been removed | |
| | | completely. | |
| | | | |
| | | | |
| | | At the same time, new events were | |
| | | | |



| | | introduced with CDS-71596 to be informed about significant changes to a session. These are signaled between the existing OpenChannel and CloseChannel events: EVT_DevSBeforeCreateSession | |
|-----------|---|--|-----------------|
| | | EVT_DevSSessionDeleted | |
| | | Since the DevGetSessionId() and ServerGetSessionId() functions were used to retrieve the associated SessionID in the event EVT_ChSChannelClosed, the event EVT_DevSSessionDeleted can simply be used here instead to get the SessionID directly as an event parameter. With other words, the EVT_DevSSessionDeleted replaces the previous combination of EVT_ChSChannelClosed and the extra call of DevGetSessionId()/ServerGetSessionId(). | |
| | | In addition, the following functions were incompatibly adapted and thereby removed from the interface of the CmplecVarAccess component, as they were intended for internal call only: | |
| | | lecVarAccCreateVarList() | |
| | | lecVarAccDeleteVarList() | |
| | | lecVarAccDeleteVarLists() | |
| | | lecVarAccDeleteAllLists() | |
| | | lecVarAccVarListGetFlags() | |
| | | lecVarAccAppendVar() | |
| | | lecVarAccRemoveVar() | |
| | | lecVarAccGetFirstVar() | |
| | | lecVarAccGetNextVar() | |
| 000 05445 | | lecVarAccInvalidateVar() | |
| CDS-65415 | UserMgr: Group derivation for rights check | [[GENERAL]] | CODESYS Control |
| | does not work | As the group in group was never | |



| | | evaluated by the runtime system this relationship has been removed. Configuration and checking access rights is not easy and strait forward when access rights are derived from on group to another. | |
|-----------|---|---|-----------------|
| | | This removed relation ship has no effect on effective access rights. | |
| CDS-74959 | VxWorks: OPCUA port 4840 down on stress test (TCP) on another port | [[GENERAL]] For more details see Advisory 2021-10, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=14806&token=637e1 2e86301b83beac1653bd88da3aa5aa3f51 b&download= | CODESYS Control |
| CDS-75073 | RTS configuration file can be modified by malicous IEC code | [[GENERAL]] For more details see Advisory 2022-02, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=17089&token=cc504 1e24fc744a397a6f6e3b78200a40e6fcd53 &download= | CODESYS Control |
| | | [[COMPATIBILITY_INFORMATION]] CODESYS Control runtime configuration files can no longer be accessed through CAA File, SysFile, SysFileAsync, or other file access libraries. | |
| CDS-75246 | WebServer: The server should not return the content of all files | [[GENERAL]] For more details see Advisory 2021-11, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=16803&token=0b8ed f9276dc39ee52f43026c415c5b38085d90a &download= | CODESYS Control |
| CDS-75308 | CmpHilscherCIFX / Profinet / Redundancy: Sporadic bus failure switching redundant plcs | [[COMPATIBILITY_INFORMATION- OEM]] The following events are renamed because of compatibility problems with 3.5.17.0 CIFX drivers: EVT_ID_CMP_PACKET_INDICATION2 => EVT_ID_CMP_PACKET_INDICATION3 | CODESYS Control |

Template: templ_tecdoc_pd_en_V1.0.docx



| | | EVT_ID_CMP_PACKET_CONFIRMATIO N2 => EVT_ID_CMP_PACKET_CONFIRMATIO | |
|-----------|--|---|-----------------|
| | | N3 | |
| CDS-75358 | Crash in CmpSettingsSrv | [[GENERAL]] | CODESYS Control |
| | when parsing crafted request | For more details see Advisory 2022-06, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=17093&token=15cd8 424832ea10dcd4873a409a09a539ee381c a&download= | |
| CDS-76136 | VxWorks: OPCUA port | [[GENERAL]] | CODESYS Control |
| | 4840 down on max. concurrent connection scan | For more details see Advisory 2021-10, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=14806&token=637e1 2e86301b83beac1653bd88da3aa5aa3f51 b&download= | |
| CDS-76140 | Web server crashes | [[GENERAL]] | CODESYS Control |
| | when subjected to HTTP header memory exhaustion attack | For more details see Advisory 2021-09, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=14805&token=f0b86f 99bb302ddd4aadec483aed5f5d3fddbf1a& download= | |
| CDS-76491 | BACnet: CmpBACnet - | [[COMPATIBILITY_INFORMATION]] | CODESYS Control |
| | BACnetOpenClientCusto mer wrong return type | FUNCTION BACnetOpenClientCustomer wrong return type was changed to IEC BACNET HANDLE. | |
| CDS-76651 | VxWorks: Implement | [[GENERAL]] | CODESYS Control |
| | SysSockGetFirstAdapterI nfo to support gateway address | Ethernet Adapters may have several default routes. Only first route is displayed. Functionality to read route information of | |
| | | | |
| CDS-77172 | SysDrv3S.sys: Local privilege escalation to system level | [[GENERAL]] For more details see Advisory 2022-03, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=17090&token=6cd08 | CODESYS Control |
| | | 8&download= | |
| CDS-76651 | exhaustion attack BACnet: CmpBACnet - BACnetOpenClientCusto mer wrong return type VxWorks: Implement SysSockGetFirstAdapterI nfo to support gateway address SysDrv3S.sys: Local privilege escalation to | <pre>which is available on the CODESYS website: https://customers.codesys.com/index.php? elD=dumpFile&t=f&f=14805&token=f0b86f 99bb302ddd4aadec483aed5f5d3fddbf1a& download= [[COMPATIBILITY_INFORMATION]] FUNCTION BACnetOpenClientCustomer wrong return type was changed to IEC_BACNET_HANDLE. [[GENERAL]] Ethernet Adapters may have several default routes. Only first route is displayed. Functionality to read route information of an Ethernet adapter is only supported for VxWorks7 and newer versions. [[GENERAL]] For more details see Advisory 2022-03, which is available on the CODESYS website: https://customers.codesys.com/index.php? elD=dumpFile&t=f&f=17090&token=6cd08 b169916366df31388d2e7ba58e7bce9350</pre> | CODESYS Control |



| To make the fix effective, you have to | |
|---|--|
| update the SysDrv3S.sys driver to latest V3.5.18.0 manually: | |
| In the Microsoft Windows Device Manager right-click on the Hilscher device to open the context menu. | |
| - Select Update driver within this. | |
| - Install the driver from the subdirectory "./Driver" of your CODESYS Development System V3 or CODESYS Control installation directory. | |
| - Check the driver version after the update. The driver must have version number 3.5.18.0. | |
| | |
| [[COMPATIBILITY_INFORMATION- EndUser]] | |
| The SysDrv3S.sys V3.5.18.0 supports the Hilscher PC fieldbus cards only. Thus, the following hardware can no longer be used with the SysDrv3S.sys driver: | |
| - "SysDrv3S Automata CAN PCI 2N" = SysDrv3S, PCI\VEN_10B5&DEV_9050&SUBSYS_34 551971" | |
| - "SysDrv3S Peak PCAN-PCI" = SysDrv3S, PCI\VEN_001C&DEV_0001&SUBSYS_00 04001C" | |
| - "SysDrv3S Peak PCAN-EXPRESS" = SysDrv3S, | |
| PCI\VEN_001C&DEV_0003&SUBSYS_00 02001C" | |
| Please contact the CODESYS support if you need to use this driver with one of the PC fieldbus cards listed above or any | |
| PC fieldbus cards listed above or any other currently unsupported hardware. | |

Template: templ_tecdoc_pd_en_V1.0.docx



| CDS-78510 | Runtime generates weak | [[GENERAL]] | CODESYS Control |
|-----------|--|---|-----------------|
| | ChannelIDs | For more details see Advisory 2022-04, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=17091&token=c450f 8bbbd838c647d102f359356386c6ea5aec a&download= | |
| | | [[COMPATIBILITY_INFORMATION- OEM]] | |
| | | The obsolete marked function NetServerGetChannelInfoByIndex() was removed completely, use NetServerGetChannelInfoByIndex3() instead. The interface between the CmpChannelClient, CmpChannelServer/CmpChannelServerE mbedded, CmpChannelMgr/CmpChannelMgrEmbed ded components was reworked, especially the L4 packet processing structures were redesigned. | |
| CDS-78845 | CmpUserMgr: anonymous login is still allowed after anonymous login is deactivated | [[GENERAL]] For more details see Advisory 2022-05, which is available on the CODESYS website: https://customers.codesys.com/index.php? eID=dumpFile&t=f&f=17092&token=a556b 1695843bb42084dc63d5bdf553ca02ea39 3&download= | CODESYS Control |
| CDS-78898 | CmpUserMgr: Relogin should support changing account | [[COMPATIBILITY_INFORMATION]] The behavior of UserMgrRelogin was extended. This function now allows to switch to another user account. If this is allowed by a session and the session builds up a cache of usernames or access rights itself (instead of using the UserMgr cache) this cache has to be cleaned up. | CODESYS Control |
| CDS-79100 | [Remove Product from Setup] [Product discontinuation] Windows CE 5 | [[GENERAL]] Win CE5 files are no longer part of PLCHandler SDK. | CODESYS Control |
| CDS-79444 | CmpTraceMgr: Denial of Service vulnerability | [[GENERAL]] | CODESYS Control |
| | | For more details see Advisory 2022-06, | |



| [| | which is evaluable on the CORECVC | |
|-----------|--------------------------|---|------------------|
| | | which is available on the CODESYS | |
| | | website: | |
| | | https://customers.codesys.com/index.php? | |
| | | eID=dumpFile&t=f&f=17093&token=15cd8 | |
| | | 424832ea10dcd4873a409a09a539ee381c | |
| | | a&download= | |
| CDS-79805 | update BACstack to | [[GENERAL]] | CODESYS Control |
| | V15.0.1.1 | | |
| | | BACstack updated to V15 to support | |
| | | BACnet protocol revision 15. | |
| | | | |
| | | [[COMPATIBILITY_INFORMATION]] | |
| | | | |
| | | BACnet protocol revision 15 forced some API (DUT) extension, | |
| | | AFT (DOT) extension, | |
| | | most notably | |
| | | BACNET_ENGINEERING_UNITS and | |
| | | IEC_BACNET_STACK_CONTROL_TYPE | |
| | | | |
| | | | |
| | | CmpBACnet provides compatibility to | |
| | | | |
| | | protocol revision 14 behaviour by mean of | |
| | | setting/keeping Device.Protocol_Revision | |
| | | to 14. | |
| | | | |
| | | BACnet protocol revision 15 behaviour is | |
| | | enabled by setting | |
| | | Device.Protocol_Revision to 15. | |
| CDS-80231 | Webserver: Possible | [[GENERAL]] | CODESYS Control |
| | crash due to out of | | |
| | bounds read | For more details see Advisory 2022-07, | |
| | | which is available on the CODESYS | |
| | | website: | |
| | | https://customers.codesys.com/index.php? | |
| | | eID=dumpFile&t=f&f=17094&token=2fb18 | |
| | | • | |
| | | 8e2213c74194e81ba61ff99f1c68602ba4d | |
| 000 77470 | | &download= | O ataura 0 a a a |
| CDS-77170 | Gateway: DOS due to | [[GENERAL]] | Gateway Server |
| | null pointer dereference | | |
| | | For more details see Advisory 2021-12, | |
| | | which is available on the CODESYS | |
| | | website: | |
| | | https://customers.codesys.com/index.php? | |
| | | elD=dumpFile&t=f&f=16804&token=d8c89 | |
| | | c887979b22fdfc9fd5c3aa3804bbb1ddbff& | |
| | | download= | |
| | | uownioau= | 1 |



2 Known Limitations

PPC VLE

The VLE variant of the PPC compiler could not be tested for this release. Therefore, we discourage the use of the 3.5.18.0 PPC compiler on VLE platforms.

Runtime VxWorks C++

The C++ implementation of the VxWorks runtime is not available for 3.5.18.0. Certain calls to the runtime from the IEC-Application may lead to runtime exceptions. For details see <u>https://jira-intern.codesys.com/browse/CDS-81167</u>.



3 OEM information from JIRA

To read up on implemented features and changes you can use your JIRA account. Please find some **example** filters below.

List of features and changes:

fixVersion IN ("V3.5 SP18 Patch 1", "V3.5 SP18 Patch 2") fixVersion IN ("V3.5 SP18 Patch 1", "V3.5 SP18 Patch 2") AND issuetype = "New Feature"

List of features and changes since CODESYS V3.5 SP18:

fixVersion IN ("V3.5 SP18", "V3.5 SP18 Patch 1", "V3.5 SP18 Patch 2")

List of issues with compatibility information and known limitations:

fixVersion IN ("V3.5 SP18 Patch 1", "V3.5 SP18 Patch 2") AND (text ~ COMPATIBILITY_INFORMATION OR text ~ KNOWN_LIMITATIONS)

4 History

| Created: | Markus Brüchle (Quality Assurance) |
|-----------|---------------------------------------|
| Reviewed: | Bernhard Reiterer (Quality Assurance) |
| Released: | Bernhard Reiterer (Quality Assurance) |